



PRODUCT BULLETIN

Generic Copy

This notice is Freescale Confidential Proprietary and is only intended for the customer listed on this notification.

ISSUE DATE: 01-Aug-2012
NOTIFICATION: 15253
TITLE: ERRATA: E500V2 HANG FOR MPC8548/7/3/5, MPC8568, MPC8533/44, MPC8572, MPC8536, P2020/10, MPC8569, P102X, P1010
EFFECTIVE DATE: 02-Aug-2012

DEVICE(S)

MPN
DS783PBGAPQ38PXD
DS783PBGAPQ38VTD
DSY783PBGAPQ38PX
DSY783PBGAPQ38VT
KCUP1011NSE2DFB
KCUP1011NSE2FFB
KCUP1011NSN2DFB
KCUP1011NSN2FFB
KCUP1011NSN2HFB
KCUP1011NXE2FFB
KCUP1011NXN2DFB
KCUP1011NXN2HFB
KCUP1012NSE2HFB
KCUP1012NSN2DFB
KCUP1012NXN2HFB
KCUP1015NSE5DFB
KCUP1015NSN5BFB
KCUP1015NSN5DFB
KCUP1015SSE5FFB
KCUP1015SXE5FFB
KCUP1016NSE5BFB
KCUP1016NSE5DFB
KCUP1020NSE2DFB
KCUP1020NSE2HFB

KCUP1020NSN2HFB
KCUP1020NXE2HFB
KCUP1020NXN2HFB
KCUP1020SSE2HFB
KCUP1021NSE2DFB
KCUP1021NSE2HFB
KCUP1021NXE2DFB
KCUP1021SSE2JFB
KCUP1025NSE5DFB
KCUP1025SSE5BFB
KCUP1025SXE5BFB
KCUP102ANXN2HFB
KSCU411209B
MPC8533EVTALFA
MPC8533EVTANGA
MPC8533EVTAQGA
MPC8533EVTARJA
MPC8533VTALFA
MPC8533VTANGA
MPC8533VTAQGA
MPC8533VTARJA
MPC8535AVTANGA
MPC8535AVTATHA
MPC8535BVTAKGA
MPC8535BVTANGA
MPC8535BVTATHA
MPC8535BVTATLA
MPC8535EBVTANGA
MPC8535EBVTAQGA
MPC8535EBVTATHA
MPC8535ECVTAKGA
MPC8536AVTAKGA
MPC8536AVTANGA
MPC8536AVTAQGA
MPC8536AVTATHA
MPC8536AVTAULA
MPC8536AVTAVLA
MPC8536BVTAKGA

MPC8536BVTANGA
MPC8536BVTATHA
MPC8536BVTAULA
MPC8536BVTAVLA
MPC8536CVTANGA
MPC8536CVTAQGA
MPC8536CVTAULA
MPC8536CVTAVLA
MPC8536EAVTAKGA
MPC8536EAVTANGA
MPC8536EAVTAQGA
MPC8536EAVTATHA
MPC8536EAVTAULA
MPC8536EAVTAVLA
MPC8536EBVTANGA
MPC8536EBVTAQGA
MPC8536EBVTATHA
MPC8536EBVTAULA
MPC8536EBVTAVLA
MPC8536ECVTAKGA
MPC8536ECVTAQGA
MPC8536ECVTATHA
MPC8536ECVTAULA
MPC8536ECVTAVLA
MPC8543ECPXAQGD
MPC8543EVTANGD
MPC8543EVTAQGD
MPC8543VTANGD
MPC8543VTAQGD
MPC8544CVTALFA
MPC8544CVTANGA
MPC8544CVTAQGA
MPC8544ECVTALFA
MPC8544ECVTANGA
MPC8544ECVTAQGA
MPC8544EVTALFA
MPC8544EVTANGA

MPC8544EVTAQGA
MPC8544EVTARJA
MPC8544VTALFA
MPC8544VTANGA
MPC8544VTAQGA
MPC8544VTARJA
MPC8545EPXANGD
MPC8545EVTANGD
MPC8545EVTATGD
MPC8545PXANGD
MPC8545PXAQGD
MPC8545PXATGD
MPC8545VTAQGD
MPC8545VTATGD
MPC8547ECPXAQGD
MPC8547ECVTAQGD
MPC8547EPXAQGD
MPC8547EPXAUJD
MPC8547EVTAQGD
MPC8547EVTATGD
MPC8547EVTAUJD
MPC8547VTAQGD
MPC8547VTATGD
MPC8547VTAUJD
MPC8548CVTAQGD
MPC8548CVTAUJD
MPC8548ECPXAQGD
MPC8548ECPXAUJD
MPC8548ECVTAQGD
MPC8548ECVTAUJD
MPC8548EPXAQGD
MPC8548EPXAUJD
MPC8548EPXAVHD
MPC8548EVTAQGD
MPC8548EVTAUJD
MPC8548EVTAVHD
MPC8548PXAQGD

MPC8548PXATGD
MPC8548PXAUJD
MPC8548VTAQGD
MPC8548VTATGD
MPC8548VTAUJD
MPC8548VTAVHD
MPC8567EVTANGG
MPC8567EVTAQGG
MPC8567EVTAUJJ
MPC8567VTANGG
MPC8567VTAQGG
MPC8567VTAUJJ
MPC8568ECVTAQGG
MPC8568EVTAQGG
MPC8568EVTAUJJ
MPC8568VTAQGG
MPC8568VTAUJJ
MPC8569CVTANKGB
MPC8569CVTAQLJB
MPC8569ECVTANKGB
MPC8569ECVTAQLJB
MPC8569EVTANKGB
MPC8569EVTAQLJB
MPC8569EVTAUNLB
MPC8569VTANKGB
MPC8569VTAQLJB
MPC8569VTAUNLB
MPC8572CLVTAULD
MPC8572CLVTAULE
MPC8572CLVTAVNE
MPC8572CVTAVNE
MPC8572ECLPXARLE
MPC8572ECLPXATLE
MPC8572ECLPXAULE
MPC8572ECLVTAULE
MPC8572ECPXARLE
MPC8572ECPXAULE
MPC8572ECPXAVNE

MPC8572ECVTARLE
MPC8572ECVTAULE
MPC8572ECVTAVNE
MPC8572ELPXARLE
MPC8572ELPXATLE
MPC8572ELPXAULE
MPC8572ELPXAVNE
MPC8572ELVTARLE
MPC8572ELVTATLE
MPC8572ELVTAULE
MPC8572ELVTAVNE
MPC8572EPXARLD
MPC8572EPXARLE
MPC8572EPXATLD
MPC8572EPXATLE
MPC8572EPXAULD
MPC8572EPXAULE
MPC8572EPXAVNE
MPC8572EVTARLE
MPC8572EVTATLE
MPC8572EVTAULD
MPC8572EVTAULE
MPC8572EVTAVNE
MPC8572LVTARLE
MPC8572LVTATLE
MPC8572LVTAULD
MPC8572LVTAULE
MPC8572LVTAVNE
MPC8572VTARLE
MPC8572VTATLD
MPC8572VTATLE
MPC8572VTAULD
MPC8572VTAULE
MPC8572VTAVNE
P1010NSE5DFA
P1010NSE5FFA
P1010NSE5HFA
P1010NSE5HHA

P1010NSN5DFA
P1010NSN5FFA
P1010NSN5HFA
P1010NSN5HHA
P1010NXE5DFA
P1010NXE5FFA
P1010NXE5HFA
P1010NXE5HHA
P1010NXN5DFA
P1010NXN5FFA
P1010NXN5HFA
P1010NXN5HHA
P1011NSE2DFB
P1011NSE2FFB
P1011NSE2HFB
P1011NSN2DFB
P1011NSN2FFB
P1011NSN2HFB
P1011NXE2DFB
P1011NXE2FFB
P1011NXE2HFB
P1011NXN2DFB
P1011NXN2FFB
P1011NXN2HFB
P1012NSE2DFB
P1012NSE2FFB
P1012NSE2HFB
P1012NSN2DFB
P1012NSN2FFB
P1012NSN2HFB
P1012NXE2DFB
P1012NXE2FFB
P1012NXE2HFB
P1012NXN2DFB
P1012NXN2FFB
P1012NXN2HFB
P1013NSE2EFB
P1013NSE2HFB

P1013NSE2LFB
P1013NSE2MHB
P1013NSN2EFB
P1013NSN2HFB
P1013NSN2LFB
P1013NSN2MHB
P1013NXE2EFB
P1013NXE2HFB
P1013NXE2LFB
P1013NXN2EFB
P1013NXN2HFB
P1013NXN2LFB
P1014NSE5DFA
P1014NSE5FFA
P1014NSE5HFA
P1014NSE5HHA
P1014NSN5DFA
P1014NSN5FFA
P1014NSN5HFA
P1014NSN5HHA
P1014NXE5DFA
P1014NXE5FFA
P1014NXE5HFA
P1014NXE5HHA
P1014NXN5DFA
P1014NXN5FFA
P1014NXN5HFA
P1014NXN5HHA
P1015NSE5BFB
P1015NSE5DFB
P1015NSE5FFB
P1015NSN5BFB
P1015NSN5DFB
P1015NSN5FFB
P1015NXE5BFB
P1015NXE5DFB
P1015NXE5FFB

P1015NXN5BFB
P1015NXN5DFB
P1015NXN5FFB
P1016NSE5BFB
P1016NSE5DFB
P1016NSE5FFB
P1016NSN5BFB
P1016NSN5DFB
P1016NSN5FFB
P1016NXE5BFB
P1016NXE5DFB
P1016NXE5FFB
P1016NXN5BFB
P1016NXN5DFB
P1016NXN5FFB
P1017NSE5BFB
P1017NSE5CFB
P1017NSE5FFB
P1017NSE5HFB
P1017NSN5BFB
P1017NSN5CFB
P1017NSN5FFB
P1017NSN5HFB
P1017NXE5HFB
P1020NSE2DFB
P1020NSE2FFB
P1020NSE2HFB
P1020NSN2DFB
P1020NSN2FFB
P1020NSN2HFB
P1020NXE2DFB
P1020NXE2FFB
P1020NXE2HFB
P1020NXN2DFB
P1020NXN2FFB
P1020NXN2HFB
P1020SSE2HFB

P1021NSE2DFB
P1021NSE2FFB
P1021NSE2HFB
P1021NSN2DFB
P1021NSN2FFB
P1021NSN2HFB
P1021NXE2DFB
P1021NXE2FFB
P1021NXE2HFB
P1021NXN2DFB
P1021NXN2FFB
P1021NXN2HFB
P1022NSE2EFB
P1022NSE2HFB
P1022NSE2LFB
P1022NSE2MHB
P1022NSN2EFB
P1022NSN2HFB
P1022NSN2LFB
P1022NSN2MHB
P1022NXE2EFB
P1022NXE2HFB
P1022NXE2LFB
P1022NXN2EFB
P1022NXN2HFB
P1022NXN2LFB
P1023NSE5BFB
P1023NSE5CFB
P1023NSN5BFB
P1023NSN5CFB
P1023NXE5CFB
P1024NSE5BFB
P1024NSE5DFB
P1024NSN5BFB
P1024NSN5DFB
P1024NXE5BFB
P1024NXE5DFB
P1024NXN5BFB

P1024NXN5DFB
P1025NSE5BFB
P1025NSE5DFB
P1025NSN5BFB
P1025NSN5DFB
P1025NXE5BFB
P1025NXE5DFB
P1025NXN5BFB
P1025NXN5DFB
P2010NSE2HFC
P2010NSE2HHC
P2010NSE2KFC
P2010NSE2KHC
P2010NSE2MFC
P2010NSE2MHC
P2010NSN2HFC
P2010NSN2HHC
P2010NSN2KFC
P2010NSN2KHC
P2010NSN2MFC
P2010NSN2MHC
P2010NXE2HFC
P2010NXE2HHC
P2010NXE2KFC
P2010NXE2KHC
P2010NXN2HFC
P2010NXN2HHC
P2010NXN2KFC
P2010NXN2KHC
P2020DAISYCHN2
P2020NSE2HFC
P2020NSE2HHC
P2020NSE2KFC
P2020NSE2KHC
P2020NSE2MFC
P2020NSE2MHC
P2020NSN2HFC
P2020NSN2HHC

P2020NSN2KFC
P2020NSN2KHC
P2020NSN2MFC
P2020NSN2MHC
P2020NXE2HFC
P2020NXE2HHC
P2020NXE2KFC
P2020NXE2KHC
P2020NXN2HFC
P2020NXN2HHC
P2020NXN2KFC
P2020NXN2KHC
SCWP2020C

This notice is Freescale Confidential Proprietary and is only intended for the customer listed on this notification.

AFFECTED CHANGE CATEGORIES

- DEVICE SPECIFICATION / ERRATA

DESCRIPTION OF CHANGE

It is possible for the CCB bus arbiter to get into an invalid state and hang the system. A very specific sequence of streamed IO snoops and retries from a congested memory system must occur just prior to a PCI/PCIe/SRIO write reaching the core for the hang to occur.

This will occur if the e500 V2 core has initiated a guarded load to PCI/PCIe/SRIO near the time that PCI/PCIe/SRIO does a write to cacheable, coherent memory, and that write is behind (or is one of) multiple full cache line writes from an IO device that hit modified in the e500's L1 data cache.

To prevent this behavior :

- Set SPR976[40:41] to b'10. The SPR register, SPR976, is the same for all affected devices.

Setting these bits will force the core to process all snoops of the IO device full cache line writes to DDR differently and will avoid the hang condition. No performance impact is experienced in using this setting. This workaround must be applied to each core of a multiple core device.

For more information please refer to the errata of the affected device and referenced as CPU: A005125.

REASON FOR CHANGE

The system could hang as a result of no further forward progress being made to and from the e500 V2 coherency module (ECM). The watchdog timer (if set) would then trigger the system to reboot. To prevent this behavior the software workaround described in the Description of Change must be implemented.

ANTICIPATED IMPACT OF PRODUCT CHANGE(FORM, FIT, FUNCTION, OR RELIABILITY)

Although the sequence of events that can trigger the e500 V2 system hang is rare, we recommend implementing the software workaround.

NOTE:

THE CHANGE(S) SPECIFIED IN THIS NOTIFICATION WILL BE IMPLEMENTED ON THE EFFECTIVE DATE LISTED ABOVE. To request further data or inquire about the notification, please enter a [Service Request](#)

For sample inquiries - please go to www.freescale.com

QUAL DATA AVAILABILITY DATE: 19-Jun-2012

QUALIFICATION STATUS: COMPLETED

QUALIFICATION PLAN:

N/A

RELIABILITY DATA SUMMARY:

N/A

ELECTRICAL CHARACTERISTIC SUMMARY:

N/A

CHANGED PART IDENTIFICATION:

N/A

SAMPLE AVAILABILITY DATE: 19-Jun-2012

ATTACHMENT(S):

External attachment(s) FOR this notification can be viewed AT:

[15253_e500v2_Hang_writeup.pdf](#)
