




- 3 For modification, etc., preventive hole for sink mark may be added according to circumstances.

△

2	PHOSPHOR BRONZE	Contact : Gold plating 0.1μm min.							
		Lead : Gold plating 0.03μm min.							
1	PPS	Under : Nickel plating 0.5μm min.		4	PVC	Cap			
		Light brown. UL94V-0		3	PVC	Tube			
NO.	MATERIAL	FINISH . REMARKS		NO.	MATERIAL	FINISH . REMARKS			
UNITS mm		SCALE 5 : 1		COUNT 1	DESCRIPTION OF REVISIONS DIS-F-00006410		DESIGNED KS. NAKAJIMA	CHECKED HT. YAMAGUCHI	DATE 20200803
 HIROSE ELECTRIC CO., LTD.		APPROVED : NH. NAKATA		20161121	DRAWING NO. EDC-150568-91-00				
		CHECKED : HT. YAMAGUCHI		20161121	PART NO. FX8-140P-SV(91)				
		DESIGNED : MT. ITANO		20161121	CODE NO. CL578-0007-2-91				
		DRAWN : MT. ITANO		20161121					
						 			

Jun.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.

Drawing for packing (free)



Notes 4 1 tube : 10 connectors.

HRS	DRAWING NO.	EDC-150568-91-00
	PART NO.	FX8-140P-SV(91)
	CODE NO.	CL578-0007-2-91

1

2

3



Jun.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.

【Precaution】

When a board with multiple connectors mounted is mated, the connector may be damaged or deformed.
Please divide one side of the board so only one connector is mated per board.

OK

NG



DRAWING NO.	EDC-150568-91-00
PART NO.	FX8-140P-SV(91)
CODE NO.	CL578-0007-2-91