



Product Change Notification

Current Date: 17-Jan-2019

TE Connectivity

Product Change Notification: P-19-016785

PCN Date: 15-JAN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Tubing products impacted by new Prop 65

Description of Changes

This PCN is to inform our customers of additional labelling on some Tubing products. The requirements of the Proposition 65 (Prop 65) a Californian Safe water and Toxic Enforcement Act of 1986 now requires that we warn customers that some of our tubing products contain Antimony in the material make up. This requirement only applies to customer in California. However, as TE cannot predict which products will arrive with customers in California we have to label all Antimony containing products, of course these products will be delivered also to customers outside of California. No Action needs to be taken by our customers outside of California unless the products you receive are directly being forwarded through the supply chain to further customer in California USA in which case the warning must accompany the product. Please share this information with your colleagues so they will also be informed.

Reason for Changes:

Product improvement.To comply with Californian Prop 65 regulations.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

16-JAN-2019

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
018307-000	NO			"1190143-6", "V4-1/16-0-SP"			
071275-000	NO			"3-1190535-5", "RNF-100-1/2-BK-FSP"			
1036874009	NO			"5-1190758-6", "VERSAFIT-2-0-SP"			
1118016003	NO			"1190816-3", "DWP-125-3/4-2-2IN"			
1372436001	NO			"3-1190995-5", "CGAT-R-12/4-0"			
1997174002	NO			"6-1191446-3", "NETM1000-4-0-SP"			
2687052007	NO			"1-1191983-0", "CGAT-18/6-0-STK"			
281255J001	NO			"4-1192083-7", "V2-11.0-0-FSP-SM"			
314363-000	NO			"5-1192379-2", "RNF-100-1/2-BU-FSP"			
3664884001	NO			"9-1198919-6", "RNF-100-3/8-0-FSP"			
403091J001	NO			"8-1193042-1", "V4-2.5-0-SP-SM"			
4177512003	NO			"6-1193147-1", "ATUM-24/6-0-STK", "ATUM-24/6-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
463453J001	NO			"5-1193475-5", "V2-2.5-0-SP-SM"			
4642074002	NO			"9-1193480-1", "RNF-150-1-0-SP"			
495001-000	NO			"6-1193701-7", "TRSA-1014/C/1/AU-KIT"			
5020022019	NO			"9-1193752-0", "RP-4800-NO.2-0-STK"			
5020024020	NO			"1193753-1", "RP-4800-NO.2-0-SP"			
5020042016	NO			"2-1193753-5", "RP-4800-NO.3-0-STK"			
5027714001	NO			"2-1193782-5", "RP-4800-NO.11-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5038104002	NO			"4-1193792-6", "DCPT-3/1.5-45-SP"			
5050094015	NO			"7-1193814-4", "RNF-100-3/16-VT-SP"			
5052884010	NO			"1193823-8", "RNF-100-3/64-9-SP"			
5052884046	NO			"RNF-100-3/64-WH-SP", "1832037-1"			
5052944058	NO			"2-1193827-9", "RNF-100-3/32-0-SP"			
5052944219	NO			"RNF-100-3/32-BK-SP", "1642525-1"			
5052954017	NO			"1-1193829-6", "RNF-100-3/32-2-SP"			
5052954041	NO			"1-1193829-8", "RNF-100-3/32-RD-SP"			
5052974021	NO			"1193831-7", "RNF-100-3/32-6-SP"			
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
5053012028	NO			"7-1193835-2", "RNF-100-1/8-4-STK"			
5053014024	NO			"8-1193835-0", "RNF-100-1/8-4-SP"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053132039	NO			"5-1193851-8", "RNF-100-1/4-9-STK"			
5053134121	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
5053192058	NO			"1193862-9", "RNF-100-1/2-0-STK"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5053242179	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
5053264039	NO			"6-1193872-4", "RNF-100-3/4-4-SP"			
5053292059	NO			"3-1193876-5", "RNF-100-1-0-STK"			
5054214012	NO			"1193896-6", "RNF-100-1/2-OR-SP"			
5054424024	NO			"9-1193898-4", "RNF-100-1/8-GN-SP"			
505868J001	NO			"7-1193905-3", "VERSAFIT-3/32-0-SP-SM"			
5058694008	NO			"8-1193905-2", "VERSAFIT-3/32-9-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5069814012	NO			"1-1193948-7", "CGPT-2.4/1.2-0-SP"			
5069844021	NO			"7-1193950-8", "CGPT-6.4/3.2-0-SP"			
5069874011	NO			"1193954-1", "CGPT-19/9.5-0-SP"			
5069904003	NO			"6-1193956-8", "CGPT-51/26-0-SP"			
5069954004	NO			"6-1193957-5", "CGPT-4.8/2.4-9-SP"			
5200262004	NO			"4-1194083-8", "CRN-3/8-0-STK"			
5200382008	NO			"6-1194084-2", "CRN-1/8-0-STK"			
5201946048	NO			"2-1194087-4", "RT-3-NO.3-0-1.25IN"			
5201976026	NO			"5-1194087-5", "RT-3-NO.2-0-1IN"			
5201976049	NO			"6-1194087-6", "RT-3-NO.2-0-1.25IN"			
5260020006	NO			"4-1194133-9", "TC-CAPS-4003-2"			
533409-000	NO			"5-1194187-7", "RNF-100-3/8-BU-FSP"			
540963-000	NO			"7-1194242-7", "RNF-100-3/8-BK-FSP"			
5509102048	NO			"1194350-1", "ATUM-12/4-0-STK", "ATUM-12/4-0"			
5597034002	NO			"5-1194417-9", "VERSAFIT-3X-3/8-9-SP"			
5677562009	NO			"5-1194493-7", "RNF-3000-3/1-0-STK"			
5677564008	NO			"6-1194493-4", "RNF-3000-3/1-0-SP"			
5677764001	NO			"4-1194503-5", "RNF-3000-1.5/0.5-6-SP"			
5677772002	NO			"5-1194503-5", "RNF-3000-3/1-6-STK"			
580317J001	NO			"1194599-3", "V2-8.0-0-FSP-SM"			
584509-000	NO			"7-1194628-1", "VERSAFIT-1-4-FSP"			
592387J001	NO			"9-1194684-4", "V2-4.0-0-SP-SM"			
651721-000	NO			"3-1195145-8", "RNF-100-3/4-RD-FSP"			
665915J001	NO			"5-1195246-8", "V2-5.0-0-SP-SM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8134334001	NO			"6-1196328-0", "CGPT-39/13-0-SP"			
8638622003	NO			"4-1196727-3", "RNF-3000-18/6-0-STK"			
900337-000	NO			"4-1196998-8", "RNF-100-3/4-WH-FSP"			
969515-000	NO			"4-1197495-3", "RNF-100-1-WH-FSP"			
CA8788-000	NO			"RNF-100-3/8-BK-1IN"			
CW8754-000	NO			"HRHF-200FR-10/226-NM", "9-1899832-8"			
NB08004001	NO						
NB09116001	NO						

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1036874009	NO			"5-1190758-6", "VERSAFIT-2-0-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
CW8754-000	NO			"HRHF-200FR-10/226-NM", "9-1899832-8"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5069814012	NO			"1-1193948-7", "CGPT-2.4/1.2-0-SP"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
314363-000	NO			"5-1192379-2", "RNF-100-1/2-BU-FSP"			
4177512003	NO			"6-1193147-1", "ATUM-24/6-0-STK", "ATUM-24/6-0-STK"			
5038104002	NO			"4-1193792-6", "DCPT-3/1.5-45-SP"			
5052884046	NO			"RNF-100-3/64-WH-SP", "1832037-1"			
5052944219	NO			"RNF-100-3/32-BK-SP", "1642525-1"			
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053134121	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
5054424024	NO			"9-1193898-4", "RNF-100-1/8-GN-SP"			
5200382008	NO			"6-1194084-2", "CRN-1/8-0-STK"			
5260020006	NO			"4-1194133-9", "TC-CAPS-4003-2"			
540963-000	NO			"7-1194242-7", "RNF-100-3/8-BK-FSP"			
5597034002	NO			"5-1194417-9", "VERSAFIT-3X-3/8-9-SP"			
584509-000	NO			"7-1194628-1", "VERSAFIT-1-4-FSP"			
969515-000	NO			"4-1197495-3", "RNF-100-1-WH-FSP"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5038104002	NO			"4-1193792-6", "DCPT-3/1.5-45-SP"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4642074002	NO			"9-1193480-1", "RNF-150-1-0-SP"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
018307-000	NO			"1190143-6", "V4-1/16-0-SP"			
5038104002	NO			"4-1193792-6", "DCPT-3/1.5-45-SP"			
5052944058	NO			"2-1193827-9", "RNF-100-3/32-0-SP"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5677764001	NO			"4-1194503-5", "RNF-3000-1.5/0.5-6-SP"			
651721-000	NO			"3-1195145-8", "RNF-100-3/4-RD-FSP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
900337-000	NO			"4-1196998-8", "RNF-100-3/4-WH-FSP"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509102048	NO			"1194350-1", "ATUM-12/4-0-STK", "ATUM-12/4-0"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281255J001	NO			"4-1192083-7", "V2-11.0-0-FSP-SM"			
580317J001	NO			"1194599-3", "V2-8.0-0-FSP-SM"			
592387J001	NO			"9-1194684-4", "V2-4.0-0-SP-SM"			
665915J001	NO			"5-1195246-8", "V2-5.0-0-SP-SM"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053264039	NO			"6-1193872-4", "RNF-100-3/4-4-SP"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
463453J001	NO			"5-1193475-5", "V2-2.5-0-SP-SM"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
580317J001	NO			"1194599-3", "V2-8.0-0-FSP-SM"			
592387J001	NO			"9-1194684-4", "V2-4.0-0-SP-SM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
071275-000	NO			"3-1190535-5", "RNF-100-1/2-BK-FSP"			
1118016003	NO			"1190816-3", "DWP-125-3/4-2-2IN"			
314363-000	NO			"5-1192379-2", "RNF-100-1/2-BU-FSP"			
4177512003	NO			"6-1193147-1", "ATUM-24/6-0-STK", "ATUM-24/6-0-STK"			
4642074002	NO			"9-1193480-1", "RNF-150-1-0-SP"			
5020024020	NO			"1193753-1", "RP-4800-NO.2-0-SP"			
5027714001	NO			"2-1193782-5", "RP-4800-NO.11-0-SP"			
5038104002	NO			"4-1193792-6", "DCPT-3/1.5-45-SP"			
5050094015	NO			"7-1193814-4", "RNF-100-3/16-VT-SP"			
5052884046	NO			"RNF-100-3/64-WH-SP", "1832037-1"			
5052944219	NO			"RNF-100-3/32-BK-SP", "1642525-1"			
5052954041	NO			"1-1193829-8", "RNF-100-3/32-RD-SP"			
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053134121	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5053242179	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
5054214012	NO			"1193896-6", "RNF-100-1/2-OR-SP"			
5054424024	NO			"9-1193898-4", "RNF-100-1/8-GN-SP"			
5058694008	NO			"8-1193905-2", "VERSAFIT-3/32-9-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5200382008	NO			"6-1194084-2", "CRN-1/8-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5201946048	NO			"2-1194087-4", "RT-3-NO.3-0-1.25IN"			
5201976026	NO			"5-1194087-5", "RT-3-NO.2-0-1IN"			
5201976049	NO			"6-1194087-6", "RT-3-NO.2-0-1.25IN"			
5260020006	NO			"4-1194133-9", "TC-CAPS-4003-2"			
533409-000	NO			"5-1194187-7", "RNF-100-3/8-BU-FSP"			
540963-000	NO			"7-1194242-7", "RNF-100-3/8-BK-FSP"			
5509102048	NO			"1194350-1", "ATUM-12/4-0-STK", "ATUM-12/4-0"			
5597034002	NO			"5-1194417-9", "VERSAFIT-3X-3/8-9-SP"			
584509-000	NO			"7-1194628-1", "VERSAFIT-1-4-FSP"			
969515-000	NO			"4-1197495-3", "RNF-100-1-WH-FSP"			
CA8788-000	NO			"RNF-100-3/8-BK-1IN"			
NB09116001	NO						

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1997174002	NO			"6-1191446-3", "NETM1000-4-0-SP"			
2687052007	NO			"1-1191983-0", "CGAT-18/6-0-STK"			
3664884001	NO			"9-1198919-6", "RNF-100-3/8-0-FSP"			
403091J001	NO			"8-1193042-1", "V4-2.5-0-SP-SM"			
4642074002	NO			"9-1193480-1", "RNF-150-1-0-SP"			
495001-000	NO			"6-1193701-7", "TRSA-1014/C/1/AU-KIT"			
5020022019	NO			"9-1193752-0", "RP-4800-NO.2-0-STK"			
5020042016	NO			"2-1193753-5", "RP-4800-NO.3-0-STK"			
5038104002	NO			"4-1193792-6", "DCPT-3/1.5-45-SP"			
5052884010	NO			"1193823-8", "RNF-100-3/64-9-SP"			
5052944058	NO			"2-1193827-9", "RNF-100-3/32-0-SP"			
5052954017	NO			"1-1193829-6", "RNF-100-3/32-2-SP"			
5052974021	NO			"1193831-7", "RNF-100-3/32-6-SP"			
5053012028	NO			"7-1193835-2", "RNF-100-1/8-4-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053014024	NO			"8-1193835-0", "RNF-100-1/8-4-SP"			
5053132039	NO			"5-1193851-8", "RNF-100-1/4-9-STK"			
5053192058	NO			"1193862-9", "RNF-100-1/2-0-STK"			
5053292059	NO			"3-1193876-5", "RNF-100-1-0-STK"			
505868J001	NO			"7-1193905-3", "VERSAFIT-3/32-0-SP-SM"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5069814012	NO			"1-1193948-7", "CGPT-2.4/1.2-0-SP"			
5069844021	NO			"7-1193950-8", "CGPT-6.4/3.2-0-SP"			
5069874011	NO			"1193954-1", "CGPT-19/9.5-0-SP"			
5069904003	NO			"6-1193956-8", "CGPT-51/26-0-SP"			
5069954004	NO			"6-1193957-5", "CGPT-4.8/2.4-9-SP"			
5200382008	NO			"6-1194084-2", "CRN-1/8-0-STK"			
5509102048	NO			"1194350-1", "ATUM-12/4-0-STK", "ATUM-12/4-0"			
5677562009	NO			"5-1194493-7", "RNF-3000-3/1-0-STK"			
5677564008	NO			"6-1194493-4", "RNF-3000-3/1-0-SP"			
5677772002	NO			"5-1194503-5", "RNF-3000-3/1-6-STK"			
592387J001	NO			"9-1194684-4", "V2-4.0-0-SP-SM"			
8134334001	NO			"6-1196328-0", "CGPT-39/13-0-SP"			
8638622003	NO			"4-1196727-3", "RNF-3000-18/6-0-STK"			
NB08004001	NO						

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4177512003	NO			"6-1193147-1", "ATUM-24/6-0-STK", "ATUM-24/6-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
5052944058	NO			"2-1193827-9", "RNF-100-3/32-0-SP"			
5053132039	NO			"5-1193851-8", "RNF-100-1/4-9-STK"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052992172	NO		RNF-100-1/8-BK-STK	"1-1193833-7", "RNF-100-1/8-BK-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5200262004	NO			"4-1194083-8", "CRN-3/8-0-STK"			
5677564008	NO			"6-1194493-4", "RNF-3000-3/1-0-SP"			

:Part Number(s) being Modified (

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5069814012	NO			"1-1193948-7", "CGPT-2.4/1.2-0-SP"			

:C Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1036874009	NO			"5-1190758-6", "VERSAFIT-2-0-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
CW8754-000	NO			"HRHF-200FR-10/226-NM", "9-1899832-8"			

:Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5020042016	NO			"2-1193753-5", "RP-4800-NO.3-0-STK"			
5509102048	NO			"1194350-1", "ATUM-12/4-0-STK", "ATUM-12/4-0"			
5677564008	NO			"6-1194493-4", "RNF-3000-3/1-0-SP"			

:C Part Number(s) being Modified

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4177512003	NO			"6-1193147-1", "ATUM-24/6-0-STK", "ATUM-24/6-0-STK"			
5201976049	NO			"6-1194087-6", "RT-3-NO.2-0-1.25IN"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1372436001	NO			"3-1190995-5", "CGAT-R-12/4-0"			
5052944058	NO			"2-1193827-9", "RNF-100-3/32-0-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			