



Jun.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.  
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



Jun.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.  
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.

# Embossed carrier tape dimension (2:1)



**HRS**

DRAWING NO.	EDC3-150573-23
PART NO.	FX8-140P-SV1(93)
CODE NO.	CL578-0047-7-93

2/3



Jun.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.  
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.

【Precaution】

When a board with multiple connectors mounted is mated, the connector may be damaged or deformed.  
Please divide one side of the board so only one connector is mated per board.

OK

NG



**HRS**

DRAWING NO.	EDC3-150573-23
PART NO.	FX8-140P-SV1(93)
CODE NO.	CL578-0047-7-93